



## Anlage: Befundsituationen

<b>Raumsituation vor der Abnahme der Textilen Wandbespannung</b>	 A wide-angle photograph of a room with ornate white ceiling and wall moldings. The walls are covered in red patterned wallpaper. A central arched doorway is visible. A small table with equipment and a ladder are in the room.
<b>Raumsituation vor der Abnahme der Textilen Wandbespannung</b>	 A photograph showing two workers on ladders removing the red patterned wallpaper from the walls. A table with equipment and a ladder are in the foreground.

<b>Detail:_ Muster_Rapport</b>	
<b>Detail:_ Farbigkeit</b>	